

	Special Process: He	at Tre	at System Assessment		
Facility Name: Paulo, St. Louis Div	rision				
Address: 5711 West Park Ave. St. Louis, MO 63110					
Phone Number: (314) 647-7500			Fax Number: (314) 647-7518		
Date of Assessment: 11/6/2023			Date of Previous Assessment: 11/9/2022		
nternal (Captive) Heat Treater (Y/N):	N N		Commercial Heat Treater	Y	
	Type(s) of Therm	al Proce	(Y/N): essing at this Facility:		
rocess Table A	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Process Table D		
Carburizing		x	Induction Heat Treating		N/A
Carbonitriding		x	Process Table E		
Carbon Restoration		x	Annealing		x
Neutral Hardening (Quench and Temper)		x	Normalizing		x
Austempering / Martempering		N/A	Stress-Relieving	Stress-Relieving	
Tempering		x	Process Table F		
Precipitation Hardening / Aging		x	Low Pressure Processing (Carburizing / Carbonitriding / Neutral Hardening)		N/A
Process Table B			Process Table G	3,	
Nitriding (Gas)		x	Sinter Hardening		N/A
Ferritic-Nitrocarburizing (Gas or Salt)		x	Process Table H		
Process Table C			Ion Nitriding		N/A
Aluminum Heat Treatment		N/A	Process Table I		
			Hot Stamping		N/A
Current Quality Certification(s): IATF	16949:2016, Ford Motor Co. Preferred	Supplier	r, General Motors High Pressure Di	e Casting Certified, Gulfstream Ap	px. 1
Date of Re-assessment (if necessary)	: N/A				
Personnel Contacted:					
lame:	Title:		Phone:	Email:	
than Castle	Key Account Manager		(314) 450-4376	ecastle@paulo.com	
Brian Heitmann	Plant Manager		(314) 450-4381	bheitmann@paulo.com	
uditors/Assessors:	1		1	1	
lame:	Company:		Phone:	Email:	
ulie Evans	Quality Assurance Manager		(314) 450-4368	jevans@paulo.com	
eo Acklin	Corporate Quality Manager		(314) 450-4405	lacklin@paulo.com	
lumber of "Not Satisfactory" Findi	ngs: 1		1	1	
lumber of "Needs Immediate Actio	n" Findings: 0				
Number of "Fail" Findings in the Jo	ob Audit(s): 0				