

<b>Special Process: Plating System Assessment Cover Sheet</b>	
Facility Name: <a href="#">Paulo Products</a>	
Address: <a href="#">1307 Rutledge Way</a> <a href="#">Murfreesboro, TN. 37129</a>	
Phone Number: <a href="#">615-896-1385</a>	
Current Quality Certification(s): <a href="#">IATF 16949, CQI-9, CQI-11, CQI-12</a>	
Number of Coating Employees at this Facility: <a href="#">10</a>	
Captive Coater (Y/N): <a href="#">No</a>	
Commercial Coater (Y/N): <a href="#">Yes</a>	
Date of Assessment: <a href="#">9-25-23</a>	
Date of Previous Assessment: <a href="#">9-29-22</a>	
Date of Re-assessment (if necessary): <a href="#">N/A</a>	
Type(s) of Plating Processing at this Facility:	
Process Table A:	Process Table F:
<a href="#">Zinc</a>	Hard Chrome Plating
Zinc Alloy Plating	
Process Table B:	Process Table G:
Mechanical Plating	Electroless Nickel
Process Table C:	Process Table H:
Decorative Plating of Metal Substrates	<a href="#">Hydrogen Embrittlement Relief Process</a>
Process Table D:	Process Table I:
Decorative Plating of Plastic Substrates	<a href="#">Process Control and Testing Equipment Verification and Calibration</a>
Process Table E:	
Electropolish and Chrome Flash	
Personnel Contacted:	
Name: <a href="#">Cristian Geist (Plating Manager)</a>	Phone: <a href="#">615-216-3007</a>
Auditors/Assessors:	
Name: <a href="#">Michael Briggs (Quality Manager)</a>	Phone: <a href="#">615-216-3014</a>
Number of Nonconforming Findings from Section 1 and Section 2:	
<a href="#">None</a>	
Number of Nonconforming Findings in the Job Audit(s):	
<a href="#">None</a>	
Number of Nonconforming Findings in the Process Table(s):	
<a href="#">None</a>	