

Special Process: Heat	Treat System Asses	ssment	
Facility Name:	Paulo - Cleveland		
Address:	Faulo - Cievelanu		
4428 Hamann Parkway			
Willoughby, OH 44094			
Phone Number:	440-946-5900	Type(s) of Thermal Processin	g at this Eacility:
Fax Number:	440-946-3091	Process Table A - Ferrous	g at this Facility.
rax Number.	440-940-3091	Carburizing	
Number of Heat Treat Employees	at this Escility:	Carbonitriding	
Number of Heat Treat Employees a		Carbon Restoration	
	126		
Internal (Captive) Heat Treater (Y/I	N): N	Neutral Hardening	
Commercial Heat Treater (Y/N):		(Quench and Temper)	
	Υ	Austempering / Martempering	
		Tempering	
Date of Assessment:	14-Aug-2023	Precipitation Hardening / Aging	
Date of Previous Assessment:	21-Sep-2022		
	,	Process Table B - Ferrous	
i		Nitriding (Gas)	
		Ferritic-Nitrocarburizing (Gas or	-
		Salt)	
		Sait)	
			1
		Process Table C - Aluminum	
		Aluminum Heat Treatment	
		Process Table D - Ferrous	
		Induction Heat Treating	
		·	
		Process Table E	
		Annealing	X
		Normalizing	X
		Stress-Relieving	X
		Otress-relieving	<u> </u>
		Process Table F	
		Low Pressure Carburizing	
		Process Table G	
		Sinter Hardening	
		Process Table H	
		Ion Nitriding	
Current Quality Certification(s):	AS9100, NADCAP		
Date of Re-assessment (if necessa	ary):		
Personnel Contacted:			
Name:	Title:	Phone:	Email:
	•		
	1	I	1
Auditors/Assessors:			
Name:	Company:	Phone:	Email:
Jack Horrigan	Quality Manager	440-510-4114	Inorrigan@paulo.com
Jack Horrigan	Quality Manager	440-310-4114	Jilorrigan@paulo.com
	1		
Name to the state of the state			
Number of "Not Satisfactory" Fir			
	0		
		_	
Number of "Needs Immediate Action" Findings:			
0			
<u> </u>			
Number of "Fail" Findings in the	.lob Audit(s):		
ramber of Tail Tillulings III the	0	 	
U			